

July 15, 2021

RE: Residence at 956 Bypass Road, Perkasie, PA 18944

To Whom It May Concern:

This letter is to confirm that Jacqueline Walker, our loyal customer for many wonderful years here at Moyer Indoor Outdoor, has consistently performed recommended annual maintenance on her Weil-McClain and Peerless oil-fired boilers on both the primary residence, and the barn building, located at 956 Bypass Road in Perkasie, PA.

The associated equipment is as follows:

- 1) Main House – Weil McClain Boiler – Model# WTG05, Serial# CP5266336
- 2) Barn Building – Peerless Boiler – Model# WBV-04-WPC, Serial# 693008-201306
- 3) Barn Building – Peerless Boiler – Model# WBV-04-WPC, Serial# 693007-201306

Jacqueline's last (3) annual maintenance appointments (including all equipment listed above) were conducted on the following dates, with the following technicians:

- 1) January 13, 2021 with Dan Weller
- 2) December 19, 2019 with Jon Orlik (Date delayed by Moyer due to COVID-19)
- 3) August 15, 2018 with Lou Marrazzi

The average cost for each system's tune-up included in a service contact per year was \$309. Jacqueline maintained the Premium contract for all of her units, which is the highest contract offered by Moyer Indoor Outdoor, and includes the highest amounts of parts and labor coverage.

The average cost for a consumer who would not elect to have parts and labor coverage and pay for all tune-ups annually and repairs at retail pricing would be \$179.

The average cost for routine service repairs due to typical wear and tear for these systems over the course of 3 years has been \$226 per year, if spread over a 3-year period.

Thank you,

Kimberley Watkins
Customer Service Manager
kim.watkins@emoyer.com